

VibrantEase

MW-ST-T-200



Installation instruction


Web: www.mwworkstation.com

Tel: +86 13695211636


Mail: robbor@mwworkstation.com

CONTENTS

01 Fixed feet



02 Return foot




VibrantEase

Fixed feet

PARTS SHOW

1



[Component]

2



2PCS

[Forelegs(Short leg)]


3



2PCS


[Rear foot(Long legs)]

4



[Back]


5



M6*35mm

[screw]


6



Ø6 Shim 4PCS

[shim]


7



M6*20mm

[screw]

8




5mm

[tool]


INSTALLATION STEPS

1




[Install chair legs]

2



INSTALLATION STEPS

3



[Mounting screws]

4




[Finish]

VibrantEase

Return foot


PARTS SHOW

1




[Bracket]

2



[Back]


3



M6*20mm
X 4PCS

[screw]


4



Ø6 Shim
X 4PCS

[Accessories]


5



5mm
[tool]

INSTALLATION STEPS


1



[Install cushion]


2

 **M6*20mm
X 4PCS**  **Ø6 Shim
X 4PCS**



[Mounting screws]

3



[Finish]



Web: mwworkstation.com

Mail: robbor@mwworkstation.com

Tel: +86 13695211636

WhatsApp: + 86 13695211636

Add: NO.3 Xingye North Road Dawotang Industrial
District Shishan Nanhai Foshan City Guangdong
P.R China



WhatsApp



Facebook



Instagram



Twitter



Pinterest



Linkein



YouTube